

FITNESS CERTIFICATE FOR SCHOOL BUILDING

(Re:GO.Ms. 20/70/PWD dt 23.01.1970)


1	Name of Officer	Bessy John
2	Name of Educational Institution with Name and location	Arch Bishop Attipetti Public School,Pachalam
3	Educational District / Sub District	Pachalam, Ernakulam
4	Classification of Building as specified in column 4 of the application for fitness certificate and size	: 3 storey RCC building
5	Period which the certificate is issued	: 2023-2024
6	Nature of defects , if any	: Nil
7	I .Foundation and basement ii . Superstructure iii . Doors and windows iv . Wood work wrought & put up country wood (mention v . Roof with short specification materials used vi . Flooring	:RR column footing and beam : Brick work in cement motar : Wood Work : Country Wood : RCC roof : Vitrified Tiles
8	Any major defects noticed which will render the building unsafe in	: Nil .
9	Whether regular maintainance work have been done properly	: Yes .
10	Whether the structure is sound or not for conducting classes	: The structure is physically sound under Normal Weather Conditions .

Certified that the building was inspected be me on 09/09/2023 and found to be fit for the period 2023 - 2024 under normal weather condition.

Place : Kochi

Date 12.09.2023




BESSY JOHN
ASSISTANT ENGINEER
LEAD
KOCHI MUNICIPAL CORPORATION